

FLOSS MAKING PROCEDURE

DOC: RM40003

RM-4.0-A

ADD SUGARS ONLY WHILE MOTOR IS RUNNING. THIS WILL ELIMINATE EXCESSIVE HAND VIBRATION. WHENEVER YOU ADD SUGAR TO THE FLOSS, ALWAYS FILL IT ABOUT 90% FULL


DO NOT OVERFILL

1. Grip cone as shown.
2. Break into web of floss with cone.
3. Lift web of floss from pan and roll onto cone.

REMEMBER!

Let the machine do the work!

KEEP HANDS AWAY FROM SPINNING HEAD!



GRIP -- ROTATION “WIND THE WEB OF SUGAR ONTO THE CONE”

